

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HAER  
NY  
98-HUFA  
2-

Glens Falls Feeder: Sluice  
Beginning 350 feet southeast of junction  
of Pine Street and Burgoyne Avenue,  
heading 600 feet along south side  
of Glens Falls Feeder, between Locks  
10 and 6.

HABS No. NY-200

Hudson Falls City  
Washington County  
New York

Photographer: (Views 1-16) Greg Troupe

August 1988

- NY-200-1 VIEW SOUTHEAST, DESTROYED HEAD OF STONE SLUICE, SHOWING SECOND  
DROP OF SLUICE TO LEFT, HEADWALL OF BARGE CANAL SLUICE TO RIGHT
- NY-200-2 VIEW SOUTHEAST, INTERIOR OF SECOND DROP, FOUNDATION AND FOOTWALL  
AND SIDEWALLS, SHOWING FAILED LOWER ARCH
- NY-200-3 INTERIOR OF SECOND DROP, EAST CORNER, UPPER ARCH
- NY-200-4 VIEW SOUTHEAST, STONE SLUICE, TOP OF UPPER STANDING SECTION,  
SHOWING CEMENT PIERS OVER ARCH IN FOREGROUND, FOOT OF BREAK AT  
THIRD DROP IN CENTER, RETAINING WALL TO LEFT, BARGE CANAL SLUICE  
TO RIGHT
- NY-200-5 VIEW NORTH, STONE SLUICE, HEAD OF 40-FOOT BREAK, SHOWING FAILED  
ARCH IN CENTER, STONE PIER IN CENTER RIGHT, CEMENT PIERS TO UPPER  
LEFT, RETAINING WALL IN BACKGROUND
- NY-200-6 VIEW EAST, STONE SLUICE, BEGINNING OF LOWER STANDING SECTION,  
SHOWING THIRD DROP, STONE PIER IN CENTER, CEMENT PIERS TO RIGHT
- NY-200-7 VIEW SOUTHEAST, INTERIOR OF THIRD DROP, FOOTWALL AND SIDEWALLS
- NY-200-8 VIEW SOUTHEAST, STONE SLUICE, TOP OF LOWER STANDING SECTION,  
SHOWING ROW OF CEMENT PIERS IN CENTER, RETAINING WALL TO LEFT,  
BARGE CANAL SLUICE TO RIGHT
- NY-200-9 LOCK 9 RETAINING WALL, SOUTHEAST FACE, SHOWING LOCK 9 TO RIGHT
- NY-200-10 VIEW NORTH, LOCK 9 RETAINING WALL, COLLAPSED CORNER AND SOUTHWEST  
FACE
- NY-200-11 VIEW NORTHWEST, BARGE CANAL SPILLWAY, SHOWING DISCHARGE BASIN  
IN CENTER, LOCK 7 RETAINING WALL TO RIGHT

(continued)

INDEX TO PHOTOGRAPHS  
Clens Falls Feeder: Sluice  
HABS No. NY-200 (Page 2)

- NY-200-12 VIEW NORTHWEST, DISCHARGE BASIN, SHOWING LOCK 7 RETAINING WALL TO UPPER RIGHT
- NY-200-13 DISCHARGE BASIN, NORTH SIDEWALL, SHOWING JUNCTION OF OLD WALL TO RIGHT AND 1889 WALL TO LEFT, LOCK 7 RETAINING WALL IN BACKGROUND
- NY-200-14 DISCHARGE BASIN, SOUTH SIDEWALL
- NY-200-15 VIEW NORTHWEST, DISCHARGE BASIN, SHOWING FOOT OF NORTH SIDEWALL, LOCK 6 RETAINING WALL TO UPPER RIGHT
- NY-200-16 VIEW NORTHWEST, DISCHARGE BASIN, FLOOR, SHOWING CEMENT CROSS BEAMS BUILT ON STONE BASES
- NY-200-17 Photocopy of photograph (from Crayer collection, Canal Society of New York State), photographer unknown, date unknown
- NY-200-18 Photocopy of print (from Augusta Brown notebook, New York State Archives and Manuscripts), photographer unknown, date unknown "Miracle of Yore"
- NY-200-19 Photocopy of photograph (from Barge Canal Contract 56, Photo Album Negative 26, New York State Archives and Manuscripts), photographer unknown, 1912  
VIEW NORTHWEST, BARCE CANAL SLUICE AROUND 5 COMBINED, UNDER CONSTRUCTION
- NY-200-20 Photocopy of photograph (from Barge Canal Contract 56, Photo Album Negative 49, New York State Archives and Manuscripts), photographer unknown, 1912  
VIEW NORTHWEST, BARCE CANAL SLUICE AROUND 5 COMBINED, COMPLETED
- NY-200-21 Photocopy of original map (from Feeder Book, New York State Archives and Manuscripts, Albany, New York), Holmes Hutchinson, surveyor, 1834
- NY-200-22 Photocopy of drawing, "Sluiceway at Combined Locks Clens Falls Feeder" (from Champlain Canal Structure Book 6-45, New York State Archives and Manuscripts, Albany, New York), c. 1858
- NY-200-23 Photocopy of drawing, "Plan of Proposed Sluice around 5 Combined Locks Clens Falls Feeder" (from Champlain Canal Structure Book 6-43, New York State Archives and Manuscripts), c. 1875

(continued)

INDEX TO PHOTOGRAPHS  
Glens Falls Feeder: Sluice  
HABS No. NY-200 (Page 3)

- NY-200-24 Photocopy of drawing, "Plan and Profile for Sluice around 5 Combined Locks Glens Falls Feeder" (from Champlain Canal Structure Book 6-13, New York State Archives and Manuscripts), 1889
- NY-200-25 Photocopy of drawing, "Plan of Discharge Basin at End of Sluice Way around Locks 6 to 10 on the Glens Falls Feeder" (from Champlain Canal Structure Book 6-12, New York State Archives and Manuscripts), 1889
- NY-200-26 Photocopy of print from microfilm, "Contract No.56, Details of Bypass, Locks 6-10, Champlain Canal Section 2, Glens Falls Feeder" (original in Structure Book for Barge Canal Contract 56-189, New York State Archives and Manuscripts), 1912